

FIG. 1






FIG. 2






FIG. 3



Forming a Contrast Image Selecting a Suitable Standard Line Adjusting the Selected Standard Line Flushing the Standard Line With the Profile of the Contrast Image Outputting the Rotary Value of the Selected Standard Line Contrasting the Rotary Values of the Selected Standard Line Outputting the Measure Value

FIG. 4






FIG. 5
PRIOR ART



